







Diagram illustrating assembly instructions and warnings:

- Warning 1:** A warning triangle with an exclamation mark is positioned above a box containing a circular icon of an L-shaped bracket and a crossed-out power drill. To the right of this box is a clock icon with the number **5'** below it, indicating a 5-minute assembly time.
- Warning 2:** A second warning triangle with an exclamation mark is positioned above a box containing a circular icon of a rectangular block on a textured surface and a crossed-out block with a screw. To the right of this box is a person icon with the number **1** below it, indicating that one person is required for this step.


A	B	C	D
			
x 1	x 1	x 1	x 4




C







B





A




D x 4

E	F	G	H
		 M4 x 15	
x 1	x 1	x 10	x 1




2

D




x 4




3




B



x 1



4



!

