














An icon showing an L-shaped metal bracket on the left and a power drill with a diagonal line through it on the right, indicating that a power drill should not be used for assembly.	A warning triangle icon with an exclamation mark inside.	A clock icon representing time.
<p>20'</p>		
An icon showing a rectangular block on a mat on the left and a block with a screw being inserted into it with a diagonal line through it on the right, indicating that screws should not be used to secure the mat.	A warning triangle icon with an exclamation mark inside.	An icon of a person representing the number of people required for assembly.
<p>1</p>		



1	2	A	B	C	D
x 1	x 4	M6 x 45 x 8	x 8	x 8	x 1

1

<p>1</p>  <p>x 1</p>	<p>2</p>  <p>x 4</p>	<p>A</p>  <p>M6 x 45</p> <p>x 8</p>	<p>B</p>  <p>x 8</p>	<p>C</p>  <p>x 8</p>	<p>D</p>  <p>x 1</p>
---	---	--	--	---	---

