



LESTARDS






Assembly instructions for the shelving unit, including tool requirements, time, and personnel.

Tools: An icon in a circle shows an Allen key and a wrench. A power drill icon is crossed out with a diagonal line, indicating it is not required.

Warning: A triangle with an exclamation mark indicates a warning.

Time: A clock icon is shown with the number **60'** below it, indicating a 60-minute assembly time.

Personnel: An icon of a person is shown with the number **2** below it, indicating that two people are required for assembly.



A1



x 1

A2



x 1

B1




x 1

B2




x 1

C




x 2

D




x 2

E




x 2

F




x 2

G




x 4

H



x 1

I




x 2

J




x 6

K




x 36

L




x 24

M




x 6

N




x 26

O




x 16

P




x 2

Q




x 18

R




x 1

S




x 24

T




x 24

U




x 8

V




x 70

W





x 4




X






x 1









3





4












5

D  x 2	H  x 1	M  M6 x 50 x 6	P  M4 x 1	Q  x 6	R  x 1
---	---	--	---	---	---



6 x 2

I  x 1	J  x 3	N  M6 x 40 x 6	P  M4 x 1	Q  x 6	R  x 1	V  x 12
---	---	--	---	---	---	--



7



N
M6
x
40
x 6

O
M6
x
20
x 8

P
M4
x 1

V
x 14

W
x 4



8

K
x 36

S
x 24

T
x 24

