







Diagram illustrating assembly instructions and safety warnings:

- Warning 1:** A warning triangle with an exclamation mark is positioned above a box containing an L-shaped metal bracket and a crossed-out power drill icon.
- Warning 2:** A second warning triangle with an exclamation mark is positioned above a box containing a rectangular block on a textured surface and a crossed-out icon of a block being lifted.
- Time:** A clock icon is shown next to the text "10'".
- Personnel:** An icon of a person is shown next to the number "2".



A	B	C	D	E
		 <p>M8 x 60</p>		
x 1	x 4	x 8	x 8	x 1

